

5/19/13

Maynard Conservation Commission
Maynard Town Hall
195 Main Street
Maynard, MA 01754

Re: Weekly Erosion Control Report (Weeks 3-5)
129 Parker Street, Maynard, MA

Dear Maynard Conservation Commission:

Goddard Consulting, LLC is pleased to submit this site inspection and erosion control report on behalf of Capital Group Properties in accordance with the approved SWPPP (EPA Tracking MAR12AI87) and the Maynard Stormwater Bylaw Permit.

SITE VISITS: Goddard has visited and inspected the site on 5/3, 5/7, and 5/15 in the course of routine site inspections and during/after notable rain events. Inspections will continue on an ongoing basis. There were few notable storms during this period, and one event of notable erosion occurred in the downgradient receiving stream on 5/15. This occurred when earthwork activities unearthed the final two previously unmapped catch basins, and their uncovering coincided with a rain event. Goddard notice the siltation in the stream within 2 hours of its first occurrence and immediately took action to contain the silty water. Specifically, the basins were blocked and abundant clean sand was used to filter and water prior to release. Within one hour the stream returned to clear flowing conditions. The other measures outlined in the approved SWPPP are in the process of being implemented.

GENERAL SITE ACTIVITIES: On-site crushing and sorting is completed. A few small piles of debris remain to be hauled away.

EROSION SPECIFIC ACTIVITIES: The following activities were performed:

- Routine street sweeping.
- Trenched dug around the building footprint and siltation fencing installed around the perimeters.
- Several riser pipes installed per the SWPPP. A few more remain to be completed.
- Trash pickup.
- The crushed pile on site was lowered to minimize wind erosion.

IMMEDIATE ACTION ITEMS NEEDED:

- All catch basins to be protected with double filter fabric on top and bottom. The edge will be sprayed with orange color surveying paint to alert traffic from tearing up fabric.
- Complete installation of sediment risers. See Plan for locations.

- Parking lot shall be inspected and swept weekly and/or before rain storm events during active demolition and quarterly or as needed post demolition given no traffic is expected at the property.


LONG-TERM ACTION ITEMS NEEDED:

- Sediment deposit shall be removed from the sediment basin if the deposit exceeds 6" and when demolition is completed.

If there are any questions concerning this submission, please do not hesitate to contact us.

Sincerely,
Goddard Consulting, LLC

by



Scott G Goddard, PWS
Professional Wetland Scientist

Distribution List via email:

- William Depietri, Capital Group Properties, LLC (wdepietri@me.com)
- Todd Lyons, JBJ Construction (tlyons@jbicc.net)